Reg. No 1995/005605/08

www.motorsport.co.za

2nd Floor, Meersig 1, Cnr. Upper Lake Lane & Constantia Boulevard, Constantia Kloof, Roodepoort e-mail: msa@motorsport.co.za Telephone (011) 675 2220

MSA DO4SA CIRCULAR 1 OF 2024

Affected parties are hereby advised that the following change to SSR 3.1 of the American Saloon (V8's)(AMS) class of the 2024 Dirt Oval 4 SA Standing Supplementary Regulations is made with immediate effect:

3.2 FRONT BUMPERS

- i) No External; Bumpers must be mounted with four mounting points, inclusive of the mounting to the internal pipe.
- ii) Bumpers will have 2 horizontal pipes and 4 uprights, 2 of the uprights shall be placed in the corners of the bumper. The other 2 uprights shall be placed at the point from the corner and the center of the vehicle on both sides.
- iii) Bumpers may not extend rearward of a point in line with the rear edge of the tyre of the front wheels and must be rounded back to the internal bumper mounting pipe via a bolt on flange or welded where it enters the body of the vehicle.
- iv) The 2 pipes shall be angled to join each at the point where they enter the body, either the upper or the lower pipe shall remain horizontal when viewed inside elevation.
- v) Centre of the front bumpers must be 450 from the ground with a 50 mm tolerance.
- vi) The 2 horizontal pipes must be a maximum of 200 mm apart.
- ii) vii) Internal bumper refer to CR 6.1 and CR 6.2

ISSUED ON BEHALF OF THE DIRT OVAL 4 SA MANAGEMENT

VIC MAHARAJ

SPORTING SERVICES MANAGER

3 May 2024 163260/144

MOTORSPORT SOUTH AFRICA IS THE ONLY RECOGNISED MOTORSPORT FEDERATION IN SOUTH AFRICA









